



Headset Services Ltd.

7 Cecil Pashley Way, Shoreham Airport, Shoreham-By-Sea, West Sussex BN43 5FF UK
Tel: Shoreham 01273 234 181 Facsimile: 01273 234 190
International Tel: 00 44 1273 234 181 International Fax: 00 44 1273 234 190



WORKSHOP REPORT

CUSTOMER:

CUSTOMER ORDER:

HSMRC NUMBER: **16770/1**

QUANTITY: **1**

ASSEMBLY PART NUMBER: **64300-210**

ASSEMBLY SERIAL NUMBER: **0438-145**

EQUIPMENT DESCRIPTION: **Headset, Airman 750, XLR 5, Telex single plug**

REPORTED DEFECT: **No Audio**

DEFECT CONFIRMED?

YES

NO

(IF NO, GIVE REASONS)

STRIP / WORK REPORT:

Fault found-Receive ok, mic low output and gives echo like sound, boomside earphone slide loose.

Work done-Replaced mic and hygiene parts. Adjusted earphone slide, resoldered poor internal phono connection. Mic output 110mV.

SAMPLE

TECHNICAL INSTRUCTION USED:

SIGNED:

DATE: