

Repair Report

Page 1

Call no:

Customer name:

Delivery Address

Inv Acc/Type:

Del Acc:

Customer Ref No:

Customer shipping instructions:

Date Unit Rec'd: 02/03/07

Date Unit completed: 02/03/07

Unit Part no: RA112-2074

Description:

Unit Serial No: 00050

Headset, Jetlite, Electret Microphone

Service type: Repair

Customer reported fault: Customer explains the reason for the repair.

Fault Found:

HSL check the item and report any faults

Action: HSL report the action which has been taken to fix the fault

Technician: MD

Mic Level: 750.0000

Notes:

Parts details:-

Product Code	Description	Quantity Chargeable	
RA112-2074 REPAIR	CALL NO:	1.00	N
PART	LABOUR AND PARTS USED AS BELOW	1.00	N
LABOUR STD REPAIR	Standard repair labour charge	1.00	Y
558766	Headband Cover , Raca Jetlite Mk II	1.00	Y

This is to certify that the item listed above has been inspected, cleaned and sanitised, repaired with genuine parts, passed our final test and inspection and is considered fit for service.

Signed: 



for Headset Services Ltd

Tel- 01273 234189 Fax- 01273 234190
E- repairs@headsetservices.com

HSL HEADSET SERVICES LIMITED

7 Cecil Pashley Way, Shoreham Airport, Shoreham-by-Sea, West Sussex, BN43 5FF, UK

Tel: +44 (0) 1273 234181 Fax: +44 (0) 1273 234190

E-mail: info@headsetservices.com Web site: www.headsetservices.com

Registered Office: Laurence Walter House, Addison Road, Chilton Industrial Estate, Sudbury, Suffolk, CO10 2YW

Registered number: 2962104

Directors: N F Smith, G W Harvey, M A Pantan



EASA145 Approved